


Shishmaref Airport

Age of Pavement
at 2001 Inspection



Shishmaref Airport

Age at Inspection

| |
|---------|
| 0 - 5 |
| 6 - 10 |
| 11 - 15 |
| 16 - 20 |
| 21 - 25 |
| 26 - 30 |
| > 30 |

Age in Years

Minimum PCI for Runway = 70
Minimum PCI for Taxiway and Aprons = 60

[] Branch Identifier
Airport Code: SHH
Site No.: 50701.01*A

